


Robin DR400/108 – BASIC PROCEDURES



Carb Heat when THR 2000 rpm or less

